May 2025 - Valve Repair and Testing

Duration	Description	Last Updated
May 21, 2025	Gill Ranch Storage will be testing a valve which needed an unexpected repair. The test will take approximately 2 hours. We will have reduced capacity on 5/21/2025. Please see the table below. We will advise if anything changes.	05/20/2025

	Injection	Withdrawal
05/21/2025	233,750	(339,000)

Please note that the information posted above is subject to change. If you have questions, please contact the Scheduling Group at 559.825.3577.